

Navigation Database Addendum

AIRAC 2206 – Issue 7

SUP MM 07/22 effective 2nd June 2022

MMMX Mexico City Lic Benito Juarez Intl

APCHs ILS Z RWY 05R, ILS Z RWY 23L

- APCH ILS Z RWY 05R: speed restriction at MX900 should read "blank".
- APCH ILS Z RWY 23L: speed restriction at MX402 should read "blank".

Navdata will be updated effective AIRAC cycle 2207.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Wednesday, 8th June 2022

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com

Navigation Database Addendum

AIRAC 2205 – Issue 19

SUP MM 07/22 effective 2nd June 2022

MMMX Mexico City Lic Benito Juarez Intl

APCHs ILS Z RWY 05R, ILS Z RWY 23L

- APCH ILS Z RWY 05R: speed restriction at MX900 should read "blank".
- APCH ILS Z RWY 23L: speed restriction at MX402 should read "blank".

Navdata will be updated effective AIRAC cycle 2207.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Wednesday, 8th June 2022

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com