



JEPPESEN[®]

NavData[®] Alert

!! URGENT !!

Date: 7 July 2010
Subject: Medan, Indonesia
Polonia Airport (WIMM)
Approach and Arrival Procedures
Cycle 1007

Incorrect Approach and Arrival Procedures

Jeppesen NavData for cycle 1007, effective 01 July 2010, contains incorrect Approach Procedure information for the ILS Rwy 05 [I05] at Polonia Airport; Medan, Indonesia (WIMM).

THEREFORE, DO NOT USE THE ILS RWY 05 [I05] APPROACH PROCEDURE IN CYCLE 1007 NAVDATA FOR POLONIA AIRPORT (WIMM)

The following Arrivals are no longer valid for NavData cycle1007 at Polonia Airport Medan, Indonesia (WIMM).

AMVIL ONE CHARLIE [AMVI1C]
DUAMO ONE CHARLIE [DUAM1C]
GOTLA ONE CHARLIE [GOTL1C]
JAMIS ONE CHARLIE [JAM11C]
JILAT ONE CHARLIE [JILA1C]
MEDIA ONE CHARLIE [MEDI1C]
MERIM ONE ALPHA [MERI1A]
PUGER ONE CHARLIE [PUGE1C]

THEREFORE, DO NOT USE THOSE ARRIVALS IN CYCLE 1007 NAVDATA FOR POLONIA AIRPORT (WIMM)

Revised coding will appear in Jeppesen NavData for cycle 1008, effective 29 July 2010.

Please refer to ILS Rwy 05 (11-1) approach chart dated 17 APR 09 for correct information. This Alert will be posted on the Jeppesen Web site:

<http://www.jeppesen.com/company/alerts/aviation-alerts.jsp?region=Pacific%20Basin..>

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:
Phone: 303-328-4445 E-mail: navdatatechsupport@jeppesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. They are distributed to affected ARINC 424 NavData users (avionics companies and other raw data users) and airlines receiving NavData directly from Jeppesen. Alerts are not distributed by Jeppesen to individual airline, business aviation or general aviation pilots, but are available to them on the Jeppesen Web site, www.jeppesen.com. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. Avionics users should consult with their database update service provider for definitive information on whether their system is affected by this Alert.