



→ Home  
→ Site Map



Downloads

Downloads



BULLETINS



CHANGE  
LOG



SERVICES



FEEDBACK



ORDER  
ARCHIVE



MY  
PROFILE

## ILS RWY 22R in KEWR coded incorrectly

« [Back](#)

**Date posted** 24/06/2010 15:00:36  
**Subject** FMS Navdata  
**Title** ILS RWY 22R in KEWR coded incorrectly  
**Data file**  
**Signed** Yes

Country: **USA**  
Subject: **ILS RWY 22R in KEWR coded incorrectly**  
Reference: **FAA**

We would like to notify our customers that ILS RWY 22R approach procedure has been coded incorrectly in Navtech database in cycle 1006 and 1007. Waypoint AYRON at distance I-JNN 4.1 on final approach track should read TALTE.

This error has been rectified for cycle 1008.