



JEPPESEN[®]
Airport Moving Map Alert

!! URGENT !!

Date: 28 June 2022
Subject: Hyderabad, India
Rajiv Gandhi Intl (VOHS)
Cycle 2206

TWY name incorrect.

Jeppesen Airport Moving Map and A816 formatted data for cycle 2206, effective 16 June 2022, contain incorrect data for Rajiv Gandhi Intl; Hyderabad, India (VOHS). TWY B3 (between TWY B and TWY E1) should read as **TWY K**.

**WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO
APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!**

Revised data will appear in Jeppesen Airport Moving Map and A816 formatted data for cycle 2207, effective 14 July 2022. Until then this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#). Please refer to the local NOTAMs for valid information.

If you have questions concerning this Airport Moving Map Alert, please contact Jeppesen Technical Support at:

U.S. Toll Free: 1-800-537-7725

Direct: 1-303-328-4170

E-mail: gisdatasupport@boeing.com

Airport Moving Map Alerts are published to advise users of significant issues in Jeppesen Airport Moving Map and A816 data which may affect aircraft ground operations. These Alerts are distributed to affected Airport Moving Map users. Different avionics equipment and computer systems use and display Airport Moving Map and data derived from A816 differently. End Airport Moving Map and A816 data users should consult with their Service Provider for definitive information on whether their system is affected by this Alert.