

Flight Safety Alert

AIRAC 2113 – Issue 2

USTP SE-4 effective 30th December 2021

KCSG Columbus

APCH ILS or LOC RWY 06

- missed approach should read: “climb to 1300 then climbing left turn to 2500 on heading 010° and CSG VORTAC R-086 to GEMMY INT/CSG 10 DME and hold , GEMMY holding: 266 DEG inbound, 1 minute, Right turn” .

Navdata will be updated effective AIRAC cycle 2201.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Wednesday, 15th December 2021

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com

Flight Safety Alert

AIRAC 2112 – Issue 5

USTP SE-4 effective 30th December 2021

KCSG Columbus

APCH ILS or LOC RWY 06

- missed approach should read: “climb to 1300 then climbing left turn to 2500 on heading 010° and CSG VORTAC R-086 to GEMMY INT/CSG 10 DME and hold , GEMMY holding: 266 DEG inbound, 1 minute, Right turn” .

Navdata will be updated effective AIRAC cycle 2201.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Wednesday, 15th December 2021

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com