

Flight Safety Alert

AIRAC 2113 – Issue 3

AIRAC AMDT LS 11/21 effective 2nd December 2021

LSZH Zurich

APCHs ILS 34 / LOC 34 / VOR 34

- ILS RWY 34 MISAP : altitude at IZS55 should read **at or below 5000ft.**
- LOC RWY 34 MISAP: altitude at IZS55 should read **at or below 5000ft.**
- VOR RWY 34 MISAP: altitude at R329E should read **at or below 5000ft.**

Navdata will be updated effective AIRAC cycle 2201.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Thursday, 23rd December 2021

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com

Flight Safety Alert

AIRAC 2112 – Issue 6

AIRAC AMDT LS 11/21 effective 2nd December 2021

LSZH Zurich

APCHs ILS 34 / LOC 34 / VOR 34

- ILS RWY 34 MISAP : altitude at IZS55 should read **at or below 5000ft.**
- LOC RWY 34 MISAP: altitude at IZS55 should read **at or below 5000ft.**
- VOR RWY 34 MISAP: altitude at R329E should read **at or below 5000ft.**

Navdata will be updated effective AIRAC cycle 2201.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Thursday, 23rd December 2021

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com