

## Flight Safety Alert

### **AIRAC 2203 – Issue 4**

**NFDD 218/21 effective 27<sup>th</sup> January 2022**

### **KLAS Las Vegas / Harry Reid Intl**

---

#### **SID RATPK3 (Runway 26L/R)**

- routing should read H259 deg [A2690+] - **DIRECT** LEELN - GLIAN [K230-] - BACCK -ALOLY - JENFR – RATPK (instead of H259 deg [A2690+; right turn] - DIRECT LEELN - GLIAN [K230-] - BACCK -ALOLY - JENFR – RATPK).

Navdata will be updated effective AIRAC cycle 2204.

Please disseminate this information to all affected crews

Lufthansa Systems  
FMS Customer Support  
Wednesday, 30<sup>th</sup> March 2022

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>  
For any inquiries, please contact [fms.support@lhsystems.com](mailto:fms.support@lhsystems.com)