

Flight Safety Alert

AIRAC 2204 – Issue 3

NOTAM MM A2494/22 effective 21st April 2022

MMAA Acapulco / Gen Juan N Alvarez Intl

APCH RNP RWY 10

Late receipt of NOTAM -

- Altitude at waypoint AA400 should read "at or above **1600 ft**".
- Vertical path angle between AA402 and RW10 should read **3.40 deg**.

Navdata will be updated effective AIRAC cycle 2205.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Wednesday, 13th April 2022

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com

Flight Safety Alert

AIRAC 2203 – Issue 8

NOTAM MM A2494/22 effective 21st April 2022

MMAA Acapulco / Gen Juan N Alvarez Intl

APCH RNP RWY 10

Late receipt of NOTAM -

- Altitude at waypoint AA400 should read "at or above **1600 ft**".
- Vertical path angle between AA402 and RW10 should read **3.40 deg**.

Navdata will be updated effective AIRAC cycle 2205.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Wednesday, 13th April 2022

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com