

Navigation Database Addendum

AIRAC 2112 – Issue 8

Bulgaria AIP – LBSF 18th June 2020

LBSF Sofia

APCH VOR RWY 27 / ILS-Y RWY 27 / LOC-Y RWY 27

Missed approach instructions should read:

climb straight ahead to SOF or 2300FT, whichever is later, turn right and climb to BOZ. At D8.1 SOF turn left to intercept QDR 234° BOZ.

At D21.0 SOF turn right to intercept R-258 SOF to enter BENG0 HLDG at the secondary fix in climbing 8000FT.

Missed approach turn limited to MAX 185Kts.

Navdata will be updated effective AIRAC cycle 2113.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Tuesday, 30th November 2021

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com

Navigation Database Addendum

AIRAC 2111 – Issue 24

Bulgaria AIP – LBSF 18th June 2020

LBSF Sofia

APCH VOR RWY 27 / ILS-Y RWY 27 / LOC-Y RWY 27

Missed approach instructions should read:

climb straight ahead to SOF or 2300FT, whichever is later, turn right and climb to BOZ. At D8.1 SOF turn left to intercept QDR 234° BOZ.

At D21.0 SOF turn right to intercept R-258 SOF to enter BENG0 HLDG at the secondary fix in climbing 8000FT.

Missed approach turn limited to MAX 185Kts.

Navdata will be updated effective AIRAC cycle 2113.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Tuesday, 30th November 2021

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com