

Navigation Database Addendum

AIRAC 2201 – Issue 3

NOTAM MU A0026/22 effective 7th January 2022

MUCL Cayo Largo del Sur / Vilo Acuna Intl

RWY 30, all APCHs for RWY 30

- **Until 7th March 2022, 1300Z, landing threshold displacement of 1200m is not included** in DB. Vertical guidance should not be used.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Monday, 10th January 2022

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com

Navigation Database Addendum

AIRAC 2113 – Issue 12

NOTAM MU A0026/22 effective 7th January 2022

MUCL Cayo Largo del Sur / Vilo Acuna Intl

RWY 30, all APCHs for RWY 30

- **Until 7th March 2022, 1300Z, landing threshold displacement of 1200m is not included** in DB. Vertical guidance should not be used.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Monday, 10th January 2022

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com