

Navigation Database Addendum

AIRAC 2203 – Issue 21

SUP HC AIRAC SUP 01/22 effective 24th March 2022

HCMF Bosaso

Runway 09

Late receipt of document -

- landing threshold displacement of 200 m is **not included** in NavDB.
- landing threshold coordinates should read **N11-16-30.17 E049-07-48.95**.

Navdata will be updated effective AIRAC cycle 2204.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Tuesday, 22nd March 2022

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com