

## Navigation Database Addendum

### AIRAC 2203 – Issue 7

NOTAM UU U0305/22 and U0306/22 effective 24<sup>th</sup> March 2022

### UHMM Magadan FIR

---

#### ATS routes

Late receipt of NOTAM –

- ATS route M137 should read „**BARIP N74-57.0 W168-58.4** (N74-57-00 W168-58-24)-ABRES-..., bidirectional FL265-FL540” .
- ATS route M151 should read “**AMATI N78-00.0 W168-58.4** (N78-00-00 W168-58-24)-LUNOG-..., bidirectional FL265-FL540” .
- ATS route M171 should read “**NALIM N86-20.4 W168-58.4** (N86-20-24 W168-58-24)-IRMAK-..., bidirectional FL265-FL540” .
- ATS route M172 should read “**PINAG N83-30.0 W168-58.4** (N83-30-00 W168-58-24)-**EKLUN N81-36.3 E162-10.2** (N81-36-18 E162-10-11)-**MABEM N76-22.4 E140-31.1** (N76-22-21 E140-31-04) -IDIMA-..., bidirectional FL265-FL540” .
- ATS route M177 should read “**NIKIN N80-49.6 W168-58.4** (N80-49-36 W168-58-24)-**UPLES N79-23.8 E166-36.5** (N79-23-49 E166-36-28) -RUTIN-..., bidirectional FL265-FL540” .
- ATS route N615 should read “**RAMEL N84-30.0 W168-58.4** (N84-30-00 W168-58-24)-**DIRGI N82-04.4 E155-00.2** (N82-04-26 E155-00-14)-TIGLA-..., bidirectional FL265-FL540” .
- ATS route N620 should read **ORVIT N79-00.0 W168-58.4** (N79-00-00 W168-58-24)-TURDI-..., bidirectional FL265-FL540” .
- ATS route N730 should read “**SALET N79-57.0 W168-58.4** (N79-57-00 W168-58-24)-ULKAS-..., bidirectional FL265-FL540” .
- ATS route N989 should read “**LURUN N85-25.0 W168-58.4** (N85-25-00 W168-58-24)-NIGES-..., bidirectional FL265-FL540” .
- ATS route **T396 missing**, “**DIRGI-EKLUN-OSLAR N80-31.2 E164-51.6** (N80-31-09 E164-51-35)-**UPLES**” , RNP4, bidirectional FL285-FL420.
- ATS route T571 should read “**LETUN N82-09.7 W168-58.4** (N82-09-39 W168-58-24)-**OSLAR-LOMRI N76-00.5 E143-28.2** (N76-00-29 E143-28-14)-IDIMA-..., bidirectional FL265-FL540” .
- ATS route **T632 missing**, **LOMRI-RUTIN**, RNP4, bidirectional FL265-FL540” .

- ATS route T640 should read "**BEKAR N76-28.2 W168-58.4** (N76-28-14 W168-58-24)-LUNOG-, bidirectional FL265-FL540.
- ATS rout T651 should read "**BEKAR-GOPAN-**, bidirectional FL265-FL540" .

Navdata will be updated effective AIRAC cycle 2204.

Please disseminate this information to all affected crews

Lufthansa Systems  
FMS Customer Support  
Tuesday, 15<sup>th</sup> March 2022

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>  
For any inquiries, please contact [fms.support@lhsystems.com](mailto:fms.support@lhsystems.com)