

Navigation Database Addendum

AIRAC 2206 – correction to Issue 4
NOTAM MUCL A1616/22 effective 18th June 2022

MUCL Cayo Largo del Sur Vilo Acuna Intl

Runway 30

From **18th June 2022** until **30th June 2022**, 1200Z

Landing threshold displacement of **1000m** is not included in the database.
Vertical guidance should not be used.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Tuesday, 21st June 2022

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com