

Navigation Database Addendum

AIRAC 2111 – Correction to Issue 2
NOTAM EPLY F6192/21 effective 20th October 2021

EPLY Leczyca

APCH PAR RWY 10, Runway 10

- RWY 10 landing threshold displacement of 480m (applicable for planes only) is **not included** in NAV DB.
- PAR RWY 10 approach **does not lead** to the displaced landing threshold.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Wednesday, 3rd November 2021

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com

Navigation Database Addendum

AIRAC 2110 – Correction to Issue 14
NOTAM EPLY F6192/21 effective 20th October 2021

EPLY Leczyca

APCH PAR RWY 10, Runway 10

- RWY 10 landing threshold displacement of 480m (applicable for planes only) is **not included** in NAV DB.
- PAR RWY 10 approach **does not lead** to the displaced landing threshold.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Wednesday, 3rd November 2021

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com