



JEPPESEN[®]

Airport Moving Map Alert

!! URGENT !!

Date: 12 July 2022

Subject: Calgary, Canada
Calgary Intl (CYYC)
Cycle 2207

Parking Stands status incorrect. Construction Area missing.

Jeppesen Airport Moving Map and A816 formatted data for cycle 2207, effective 14 July 2022, contain incorrect data for Calgary Intl; Calgary, Canada (CYYC). Calgary International Airport introduced Temporary Construction Activities, effective 28 March 2022, affecting Parking Stands near Air Terminal Building, between Concourse B and C. Changes are not reflected in cycle 2207 data, as do not cover entire AIRAC cycle.

Following changes are valid until approximately 30 July 2022:

- Parking Stands 31A, 31B, 33, 35B, 50, 52 are closed
- Construction Area (north of Stands 35B, 54) is added

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!


Revised data will appear in Jeppesen Airport Moving Map and A816 formatted data for cycle 2208, effective 11 August 2022. Until then this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#). Please refer to the local NOTAMs and Calgary, Canada (CYYC) 10-8 chart dated 18 MAR 22 for valid information.

If you have questions concerning this Airport Moving Map Alert, please contact Jeppesen Technical Support at:
U.S. Toll Free: 1-800-537-7725
Direct: 1-303-328-4170
E-mail: GISDataSupport@boeing.com

Airport Moving Map Alerts are published to advise users of significant issues in Jeppesen Airport Moving Map and A816 data which may affect aircraft ground operations. These Alerts are distributed to affected Airport Moving Map users. Different avionics equipment and computer systems use and display Airport Moving Map and data derived from A816 differently. End Airport Moving Map and A816 data users should consult with their Service Provider for definitive information on whether their system is affected by this Alert.

CYYC_2207

CONSTRUCTION ACTIVITIES
(UNTIL APPROXIMATELY 30 JULY 2022)



Changes to operations:

- Closure of gates 31, 33, 35B, 50, 52.
- Removal of disconnect point B5.