



JEPPESEN[®]

Airport Moving Map Alert

!! URGENT !!

Date: 16 May 2022

Subject: Varna, Bulgaria
Varna (LBWN)
Cycle 2204 and 2205

Stands layout incorrect. TWYs names incorrect.

Jeppesen Airport Moving Map and A816 formatted data for cycle 2204, effective 21 April 2022, and for cycle 2205, effective 19 May 2022, contain incorrect data for Varna; Varna, Bulgaria (LBWN). Bulgaria AIP SUP 03/22, published 06 May 2022, effective 16 May 2022, introduced “Construction works at Varna aerodrome” for the extension of the apron, which are now completed. Following changes (effective 16 May 2022) are not reflected in the data, as SUP was received after 2204 AIRAC cycle data processing due date:

- Parking Stands 5A, 14A, 16 are withdrawn
- Parking Stands 17A, 19A, 25, 26 are added
- Parking Stand 15 is relocated
- TWY A (between TWY E and TWY B) is renamed to TWY N
- TWY E (between new Stand 15 and TWY B) is renamed to TWY S

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

Revised data will appear in Jeppesen Airport Moving Map and A816 formatted data for cycle 2206, effective 16 June 2022. Until then this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#). Please refer to the local NOTAMs and Varna, Bulgaria (LBWN) 10-9A chart dated 20 May 2022 for valid information.

If you have questions concerning this Airport Moving Map Alert, please contact Jeppesen Technical Support at:

U.S. Toll Free: 1-800-537-7725

Direct: 1-303-328-4170

E-mail: gisdatasupport@boeing.com


Airport Moving Map Alerts are published to advise users of significant issues in Jeppesen Airport Moving Map and A816 data which may affect aircraft ground operations. These Alerts are distributed to affected Airport Moving Map users. Different avionics equipment and computer systems use and display Airport Moving Map and data derived from A816 differently. End Airport Moving Map and A816 data users should consult with their Service Provider for definitive information on whether their system is affected by this Alert.

LBWN_2204_2205

LBWN/VAR

20 MAY 22 **JEPPESEN** (10-9A)

VARNA, BULGARIA
VARNA



INS COORDINATES

STAND No.	COORDINATES	STAND No.	COORDINATES
1, 1A, 2	N43 14.1 E027 49.9	14 thru 15	N43 14.1 E027 49.4
3, 3A, 4	N43 14.1 E027 49.8	17 thru 18	N43 14.2 E027 49.4
5 thru 7	N43 14.1 E027 49.7	19 thru 21	N43 14.2 E027 49.5
8 thru 10	N43 14.1 E027 49.6	22 thru 23	N43 14.2 E027 49.6
11 thru 13	N43 14.1 E027 49.5	24 thru 25	N43 14.2 E027 49.7
		26	N43 14.1 E027 49.8

CHANGES: Twys, stands, limitations, coords.

© JEPPESEN, 1997, 2022. ALL RIGHTS RESERVED.