



JEPPESEN[®]

Airport Moving Map Alert

!! URGENT !!

Date: 03 June 2022

Subject: Krabi, Thailand
Krabi (VTSG)
Cycle 2205 and 2206

Stands and TWYs layout incorrect.

Jeppesen Airport Moving Map and A816 formatted data for cycle 2205, effective 19 May 2022, and for cycle 2206, effective 16 June 2022, contain incorrect data for Krabi; Krabi, Thailand (VTSG). Thailand AIP SUP B 05/22, published 02 June 2022, effective 03 June 2022, introduced “Opening of New Apron at Krabi airport (VTSG)”. SUP was received after 2205 and 2206 AIRAC cycles data processing due dates, and as a result, following changes are not reflected in the data:

- Apron (northwest of Parking Stand 8) is added
- Parking Stands 1/1L/1R, 9, 10/10L/10R – 19/19L/19R and 20 are added
- Parking Stands 2L – 4L are renamed to 2R – 4R
- Parking Stands 2R – 4R are renamed to 2L – 4L
- TWY A is renamed to TWY B
- TWY B is renamed to TWY A
- TWY C (parallel to RWY 14/32) is renamed to unknown
- TWY C (perpendicular to RWY 14/32) is extended west and connects to the new Apron (abeam new Parking Stands 17R and 18L)
- TWY (between new Apron and TWY C (parallel to RWY 14/32) abeam new Parking Stand 13R) is added
- TWY (between TWY C (parallel to RWY 14/32) and RWY 14/32 (between new TWY B and TWY C)) is added and closed
- TWY (between TWY C and new Stand 20) is added and closed

If you have questions concerning this Airport Moving Map Alert, please contact Jeppesen Technical Support at:

U.S. Toll Free: 1-800-537-7725

Direct: 1-303-328-4170

E-mail: gisdatasupport@boeing.com

Airport Moving Map Alerts are published to advise users of significant issues in Jeppesen Airport Moving Map and A816 data which may affect aircraft ground operations. These Alerts are distributed to affected Airport Moving Map users. Different avionics equipment and computer systems use and display Airport Moving Map and data derived from A816 differently. End Airport Moving Map and A816 data users should consult with their Service Provider for definitive information on whether their system is affected by this Alert.

VTSG_2205_2206

**WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO
APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!**

Revised data will appear in Jeppesen Airport Moving Map and A816 formatted data for cycle 2207, effective 14 July 2022. Until then this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#). Please refer to the local NOTAMs for valid information.

If you have questions concerning this Airport Moving Map Alert, please contact Jeppesen Technical Support at:

U.S. Toll Free: 1-800-537-7725

Direct: 1-303-328-4170

E-mail: gisdatasupport@boeing.com

Airport Moving Map Alerts are published to advise users of significant issues in Jeppesen Airport Moving Map and A816 data which may affect aircraft ground operations. These Alerts are distributed to affected Airport Moving Map users. Different avionics equipment and computer systems use and display Airport Moving Map and data derived from A816 differently. End Airport Moving Map and A816 data users should consult with their Service Provider for definitive information on whether their system is affected by this Alert.