

Flight Safety Alert

AIRAC 2204 – Issue 2

AIRAC AMDT 01/22 effective 24th February 2022

ROMD Minami Daito

APCH VOR 02

- MDE transition, outbound track should read MDE VOR R-**219**.

Navdata will be updated effective AIRAC cycle 2205.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Wednesday, 13th April 2022

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com

Flight Safety Alert

AIRAC 2203 – Issue 7

AIRAC AMDT 01/22 effective 24th February 2022

ROMD Minami Daito

APCH VOR 02

- MDE transition, outbound track should read MDE VOR R-**219**.

Navdata will be updated effective AIRAC cycle 2205.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Wednesday, 13th April 2022

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com