

Navigation Database Addendum

AIRAC 2113 – Issue 1

NOTAM A6347/21 effective 23rd November 2021

SAAR Rosario Islas Malvinas

Runway 20

RWY 20 THR displacement of 310m **not** included in DB.

Vertical guidance should **not** be used.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Wednesday, 24th November 2021

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com

Navigation Database Addendum

AIRAC 2112 – Issue 6

NOTAM A6347/21 effective 23rd November 2021

SAAR Rosario Islas Malvinas

Runway 20

RWY 20 THR displacement of 310m **not** included in DB.

Vertical guidance should **not** be used.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Wednesday, 24th November 2021

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com