

Navigation Database Addendum

AIRAC 2201 – Cancellation of Issue 1 **NOTAM MU A0039/22**

MUCL Cayo Largo del Sur / Vilo Acuna Intl

RWY 12, all APCHs for RWY 12

- **Until 25th February 2022, 2145, landing threshold displacement of 1200 m is not included** in DB. Vertical guidance should not be used.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Monday, 10th January 2022

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com

Navigation Database Addendum

AIRAC 2113 – Cancellation of Issue 11 **NOTAM MU A0039/22**

MUCL Cayo Largo del Sur / Vilo Acuna Intl

RWY 12, all APCHs for RWY 12

- **Until 25th February 2022, 2145, landing threshold displacement of 1200 m is not included** in DB. Vertical guidance should not be used.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Monday, 10th January 2022

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com