

## Navigation Database Addendum

### **AIRAC 2203 – Issue 17**

**NOTAM G0196/22, G0197/22, G0199/22 and G0200/22 effective 24th March 2022**

### **VEIM Imphal**

---

#### **SID LIGSA 3A, LIGSA 3B, POREG 3A and POREG 3B**

- LIGSA 3A RW04 should read “... **R355P 355DEG/23.8NM – LIGSA.**”
- LIGSA 3B RW22 should read “... **IIM 355DEG/39.8NM – LIGSA.**”
- PORE 3A RW04 should read “... **IIM 249DEG/65.2NM – POREG.**”
- PORE 3B RW22 should read “... **R249J 249DEG/55.2NM - POREG.**”

Navdata will be updated effective AIRAC cycle 2204.

Please disseminate this information to all affected crews

Lufthansa Systems  
FMS Customer Support  
Monday, 21<sup>st</sup> March 2022

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>  
For any inquiries, please contact [fms.support@lhsystems.com](mailto:fms.support@lhsystems.com)