

Navigation Database Addendum

AIRAC 2204 – Issue 10

NOTAM MU A0902/22 effective 15th April 2022

MUCL Cayo Largo del Sur / Vilo Acuna Intl

All APCHs for RWY 12, RWY 12

From 15th April until 15th May 2022, 1300Z –

- Landing **threshold displacement of 1500m is not included in DB.**
Vertical guidance **should not** be used.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Thursday, 14th April 2022

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com

Navigation Database Addendum

AIRAC 2203 – Issue 35

NOTAM MU A0902/22 effective 15th April 2022

MUCL Cayo Largo del Sur / Vilo Acuna Intl

All APCHs for RWY 12, RWY 12

From 15th April until 15th May 2022, 1300Z –

- Landing **threshold displacement of 1500m is not included in DB.**
Vertical guidance **should not** be used.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Thursday, 14th April 2022

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com