

Navigation Database Addendum

AIRAC 2206 – Issue 20

AIRAC AMDT 06/19 effective 23rd May 2019

EDDM Munich

Waypoint DM430, DM432, DM437, DM440, DM442, DM447, DM449, DM468

Following off route WPTs are missing in the data base:

- DM430: **N48-18.9 E011-10.7** (N48-18-56.38 E011-10-39.93)
- DM432: **N48-21.1 E011-37.1** (N48-21-04.31 E011-37-07.77)
- DM437: **N48-22.7 E011-58.2** (N48-22-41.45 E011-58-11.98)
- DM440: **N48-17.7 E011-10.9** (N48-17-42.71 E011-10-53.61)
- DM442: **N48-19.7 E011-36.1** (N48-19-44.75 E011-36-08.49)
- DM447: **N48-21.4 E011-57.2** (N48-21-21.95 E011-57-12.15)
- DM449: **N48-23.3 E012-23.7** (N48-23-18.42 E012-23-43.24)
- DM468: **N48-09.3 E012-29.2** (N48-09-15.19 E012-29-13.15)

Navdata will be updated effective AIRAC cycle 2207.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Friday, 24th June 2022

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com