

Universal Avionics Navigation Database Alert

NOTE: You must make this information available to appropriate crew members or customers immediately!

Date: April 6, 2022

Subject: Helicopter RNAV approach procedures with SBAS Level of Service incorrectly included Cycle 2203

To: UNS-1 FMS SCNs 802-803, 902-903
Helicopter Database Operators

The following Universal Avionics navigation databases applicable to Software Control Numbers (SCNs) 802.X/902.X and 803.X/903.X contain incorrect data for Cycle 2203, effective 24 March 2022.

- 802-AH
- 802-BH
- 802-GHC
- 802-CZ

Helicopter RNAV approach procedures with SBAS authorization required were inadvertently provided in these databases. FMS SCNs 802.X/902.X and 803.X/903.X do not support SBAS operations.

The following approaches are affected:

- Anaktuvuk Pass, Alaska, USA (PAKP) RNAV 200
- Cles Hospital, Italy (DT71) RNAV Z 356
- Trento/Mattarello, Italy (LIDT) RNAV Z 166
- Graz LKH, Austria (LOGH) RNAV 328

THEREFORE, DO NOT USE THESE APPROACHES IN THE CYCLE 2203 UNIVERSAL AVIONICS NAVIGATION DATABASES LISTED ABOVE.

This issue has been corrected in Cycle 2204.

For additional assistance or support, please contact Universal Avionics Customer Support.

Customer Support

Tel: (800) 595-5906 • (520) 573-7627

Email: customersupport@uasc.com