

## Navigation Database Addendum

### **AIRAC 2110 – Correction to Issue 8** **NOTAM A0314/21 effective 12th October 2021**

### **FNLU Luanda / 4th of February**

---

- Work in progress involving temporarily displaced thresholds for runways 05 and 23 **has been cancelled**.
- Approaches **LOC 23, NDB 23, RNAV (GNSS) 23 and VOR/DME 23** feature raised altitudes at their respective missed approach points which **do NOT lead to the permanent landing threshold**.

Planned work in progress may be subject to begin at a future date. Please consult NOTAM for latest information.

Navdata will be updated effective AIRAC cycle 2111.

Please disseminate this information to all affected crews

Lufthansa Systems  
FMS Customer Support  
Tuesday, 12<sup>th</sup> October 2021

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>  
For any inquiries, please contact [fms.support@lhsystems.com](mailto:fms.support@lhsystems.com)