



JEPPESEN[®]

NavData[®] Alert

!! URGENT !!

Date: 22 Dec 2011

Subject: Chile
 Airways UW101, UW109, UW115 and UW117
 Cycle 1113

Missing ATS routes within Chile

Jeppesen NavData for cycle 1113 effective 15 Dec 2011 is missing Chile Airways UW101, UW109, UW115, UW117. Chile Amendment 35/11 removed the airways and NOTAM A1849/11 added them back after cycle 1113 data was released.

THEREFORE, USE CAUTION WHEN USING THE BELOW MENTIONED AIRWAYS FOR CYCLE 1113 NAVDATA

UW-101 PUERTO MONT (MON) VOR and BALMACEDA (BAL) VOR.

Starting Fix	Ending Fix	Distance	MEA	Forward/Reverse Bearings
Puerto Mont VOR	Puerto Aguirre (PAR) VOR	225 NM	FL 250	175° / 353°
Puerto Aguirre VOR	Balmaceda VOR	89 NM	FL 250	110° / 289°

UW-109 One-way NE-bnd CONCEPCION (CAR) VOR and SANTIAGO (AMB) VOR.

Starting Fix	Ending Fix	Distance	MEA	Forward/Reverse Bearings
Concepcion VOR	ESCOT	100 NM	FL 250	023° / 203°
ESCOT	Santiago VOR	129 NM	FL 250	026° / 206°

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

Phone: 303-328-4445

E-mail: navdatatechsupport@jeppesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. They are distributed to affected ARINC 424 NavData users (avionics companies and other raw data users) and airlines receiving NavData directly from Jeppesen. Alerts are not distributed by Jeppesen to individual airline, business aviation or general aviation pilots, but are available to them on the Jeppesen Web site, www.jeppesen.com. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. Avionics users should consult with their database update service provider for definitive information on whether their system is affected by this Alert.

UW-115 PUNTA ARENAS (NAS) VOR and PUERTO WILLIAMS (PWL) VOR.

Starting Fix	Ending Fix	Distance	MEA	Forward/Reverse Bearings
Punta Arenas (NAS) VOR	ALMIR	71 NM	FL 250	135° / 315°
ALMIR	DARIN	68 NM	FL 250	135° / 315°
DARIN	Puerto Williams (PWL) VOR	39 NM	FL 250	074° / 254°

UW-117 One-way SW-bnd SANTIAGO (AMB) VOR and CONCEPCION (CAR) VOR.

Starting Fix	Ending Fix	Distance	MEA	Forward/Reverse Bearings
Santiago (AMB) VOR	LINER	30 NM	FL 250	174° / 354°
LINER	Curico (ICO) VOR	67 NM	FL 250	196° / 016°
Curico (ICO) VOR	MAULE	29 NM	FL 250	198° / 018°
MAULE	Concepcion (CAR) VOR	112 NM	FL 250	218° / 038°

Revised coding will appear in Jeppesen NavData for cycle 1201, effective 12 Jan 2012. Until then an entry will appear in the NavData Change Notices beginning 16 Dec 2011, and this Alert will be posted on the Jeppesen Web site (<http://www.jeppesen.com/company/alerts/aviation-alerts>).

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

Phone: 303-328-4445

E-mail: navdatatechsupport@jeppesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. They are distributed to affected ARINC 424 NavData users (avionics companies and other raw data users) and airlines receiving NavData directly from Jeppesen. Alerts are not distributed by Jeppesen to individual airline, business aviation or general aviation pilots, but are available to them on the Jeppesen Web site, www.jeppesen.com. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. Avionics users should consult with their database update service provider for definitive information on whether their system is affected by this Alert.