



JEPPESEN.

NavData® Alert

!! URGENT !!

Date: 6 August 2010

Subject: Minot, North Dakota
Minot AFB (KMIB)
ILS or LOC DME Rwy 11 [I11]
ILS or LOC DME Rwy 29 [I29]
TACAN Rwy 11 [T11]
TACAN Rwy 29 [T29]
Cycle 1008

Procedure changes postponed

Jeppesen NavData for cycle 1008, effective 29 July 2010, contains incorrect Approach Procedure information for Minot AFB; Minot, North Dakota (KMIB). The Military Source provider has postponed the procedure changes at Minot AFB until cycle 1010, effective 23 September 2010.

THEREFORE, DO NOT USE THE APPROACH PROCEDURES LISTED BELOW IN CYCLE 1008 NAVDATA FOR MINOT AFB:

ILS or LOC DME Rwy 11 [I11]
ILS or LOC DME Rwy 29 [I29]
TACAN Rwy 11 [T11]
TACAN Rwy 29 [T29]

Revised coding will appear in Jeppesen NavData for cycle 1009, effective 26 August 2010. Until then an entry will appear in the NavData Change Notices beginning 20 AUG 10, and this Alert will be posted on the Jeppesen Web site (<http://www.jeppesen.com/company/alerts/aviation-alerts.jsp?region=United%20States>). Jeppesen charts are also affected and will be posted on this website as soon as they are available.

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

Phone: 303-328-4445

E-mail: navdatatechsupport@jeppesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. They are distributed to affected ARINC 424 NavData users (avionics companies and other raw data users) and airlines receiving NavData directly from Jeppesen. Alerts are not distributed by Jeppesen to individual airline, business aviation or general aviation pilots, but are available to them on the Jeppesen Web site, www.jeppesen.com. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. Avionics users should consult with their database update service provider for definitive information on whether their system is affected by this Alert.

KMIB 1008