



!! URGENT !!

Date: 2 April 2021

Subject: Tabriz, Iran
Tabriz Intl (OITT)
RWY 12L/30R SID UROMIYEH 1A/1B
Cycle 2103

Procedures missing from database

Jeppesen NavData for cycle 2103, effective 25 March 2021, contains incorrect data for Airport Tabriz Intl, Iran (OITT). Procedures **RWY 12L/30R SID UROMIYEH 1A/1B** are missing from the database. NOTAM A0981/21 was received after the ICAO specified date for aeronautical information publication.

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

Revised coding will appear in Jeppesen NavData for cycle 2104, effective 22 April 2021. Until then an entry will appear in the NavData Change Notices and this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#).

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:
+1-303-328-4445 (Western Hemisphere)
+49 610 250 8175 (Eastern Hemisphere)
E-mail: navdatatechsupport@jeppesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.

OITT_2103